



Red and White Fire Protection Limi

Unit 8, Alpha Business Park

0800 058 8946

Travellers Close

info@redandwhitefireprotection.co.uk

Welham Green

www.redandwhitefireprotection.co.uk

Herts, AL9 7NT

FIRE EXTINGUISHER SERVICE INSPECTION CERTIFICATE

Client: St Andrews Church

Address: Silver Street, Enfield, EN13NG

This is to certify that a representative of Red and White Fire Protection Ltd has recently visited your premises to service your portable fire extinguishers and, apart from the non conforming extinguishers detailed, they have been serviced as required by British Standard BS 5306: part 3 2017. Certification is reliant on all extinguishers being in good, working and serviceable condition. If any equipment is found to be non conforming and could not be rectified at time of service, a recommendation to rectify will be supplied.

Date of Service: 12/12/2023

Job Reference: 23-12-01995

Next Service Due: 12/12/2024

Engineer: AC



Red and White Fire Protection Limi

Unit 8, Alpha Business Park

0800 058 8946

Travellers Close

info@redandwhitefireprotection.co.uk

Welham Green

www.redandwhitefireprotection.co.uk

Herts, AL9 7NT

GUIDANCE TO CLIENTS

Apart from the non-conforming extinguishers recorded, all portable fire extinguishers have been inspected and serviced in accordance with BS 5306 Part 3, BAFE Scheme BSP101.

Clients, however, are reminded of the recommendations given in BS 5306 Part 3 for their own inspection:

It is recommended that regular visual inspections of all extinguishers be carried out by the user or the user's representative. The frequency of inspections should be at least monthly and, when circumstances require, inspections should be carried out more frequently.

NOTE 1 The "Fire Safety: An Employer's Guide [10]" information leaflet for employers, which is published by the Home Office as guidance for operating within the Fire Precautions (Workplace) Regulations [2] and [3], suggests that good practice is to determine whether the extinguisher has been operated and to check for damage on a weekly basis.

Inspections should include checks that:

- a) each extinguisher is located in the designated place;
- b) each extinguisher is unobstructed and visible;
- c) the operating instructions for each extinguisher are clean and legible, and face outwards;
- d) each extinguisher has not been operated and is not obviously damaged;
- e) the reading of any pressure gauge or indicator fitted to an extinguisher is within operational safety limits;
- f) the seals and tamper indicators of each extinguisher are not broken or missing.

The client should arrange for corrective action, where necessary.

NOTE 2 Employers in charge of a workplace have an obligation under the Fire Precautions (Workplace) Regulations [2] and [3]. Regulation [6] requires that, where it is necessary to provide extinguishing equipment to safeguard employees in the event of fire, this equipment has to be maintained in an efficient state, in efficient working order, and in good repair.



6 litre Water Extinguisher

Asset No 1 Location Church side entrance Next Test 09-2026
Service Condemn Recharge Refurbish Discharge CallOut New

2kg Carbon Dioxide Extinguisher

Asset No 2 Location Church vestry Next Test 09-2025
Service Condemn Recharge Refurbish Discharge CallOut New

2kg Carbon Dioxide Extinguisher

Asset No 3 Location Church organ Next Test 09-2024
Service Condemn Recharge Refurbish Discharge CallOut New

6 litre Water Extinguisher

Asset No 4 Location Church fire exit rear Next Test 09-2025
Service Condemn Recharge Refurbish Discharge CallOut New

6 litre Water Extinguisher

Asset No 5 Location Chchurch side entrance Next Test 09-2025
Service Condemn Recharge Refurbish Discharge CallOut New

2kg Carbon Dioxide Extinguisher

Asset No 6 Location Church rear room Next Test 09-2030
Service Condemn Recharge Refurbish Discharge CallOut New

6 litre Foam Extinguisher

Asset No 7 Location Church bell tower Next Test 09-2028
Service Condemn Recharge Refurbish Discharge CallOut New Unit expired - replaced at time of service

2kg Carbon Dioxide Extinguisher

Asset No 8 Location Church bell tower Next Test 09-2024
Service Condemn Recharge Refurbish Discharge CallOut New



INSPECTION SCHEDULE

2kg Carbon Dioxide Extinguisher

Asset No 9 Location Hut Next Test 09-2025
Service Condemn Recharge Refurbish Discharge CallOut New

6 litre Foam Extinguisher

Asset No 10 Location Hut Next Test 09-2025
Service Condemn Recharge Refurbish Discharge CallOut New

1.2m x 1.2m Fire Blanket

Asset No 11 Location Vicarage kitchen Next Test 10-2020
Service Condemn Recharge Refurbish Discharge CallOut New

6 litre Water Extinguisher

Asset No 12 Location Floor 1 Vicarage stairwell Next Test 10-2026
Service Condemn Recharge Refurbish Discharge CallOut New

2kg Carbon Dioxide Extinguisher

Asset No 13 Location Floor 1 Vicarage studio Next Test 10-2031
Service Condemn Recharge Refurbish Discharge CallOut New

6 litre Water Extinguisher

Asset No 14 Location Ground vicarge entrance Next Test 10-2026
Service Condemn Recharge Refurbish Discharge CallOut New

2kg Carbon Dioxide Extinguisher

Asset No 15 Location Ground vicarage entrance Next Test 10-2031
Service Condemn Recharge Refurbish Discharge CallOut New

6 litre Water Extinguisher

Asset No 16 Location Ground vicarage hallway/stairs Next Test 10-2026
Service Condemn Recharge Refurbish Discharge CallOut New



Red and White Fire Protection Limi

Schedule 23-12-01995

INSPECTION SCHEDULE

Inspected 12/12/2023

Recommendations / Additional Notes

Annual service 2023 - 1 x Foam extinguisher expired - replaced.