



## Red and White Fire Protection Limited

Unit 8, Alpha Business Park

0800 058 8946

Travellers Close

[info@redandwhitefireprotection.co.uk](mailto:info@redandwhitefireprotection.co.uk)

Welham Green

[www.redandwhitefireprotection.co.uk](http://www.redandwhitefireprotection.co.uk)

Herts, AL9 7NT

# FIRE EXTINGUISHER SERVICE INSPECTION CERTIFICATE

Client: St Andrews Church

Address: Silver Street, Enfield, EN13NG

*This is to certify that a representative of Red and White Fire Protection Ltd has recently visited your premises to service your portable fire extinguishers and, apart from the non conforming extinguishers detailed, they have been serviced as required by British Standard BS 5306: part 3 2017. Certification is reliant on all extinguishers being in good, working and serviceable condition. If any equipment is found to be non conforming and could not be rectified at time of service, a recommendation to rectify will be supplied.*

Date of Service: 21/10/2021

Job Reference: 21-10-00764

Next Service Due: 21/10/2022

Engineer: 009



# Red and White Fire Protection Limited

Unit 8, Alpha Business Park

0800 058 8946

Travellers Close

[info@redandwhitefireprotection.co.uk](mailto:info@redandwhitefireprotection.co.uk)

Welham Green

[www.redandwhitefireprotection.co.uk](http://www.redandwhitefireprotection.co.uk)

Herts, AL9 7NT

## GUIDANCE TO CLIENTS

Apart from the non-conforming extinguishers recorded, all portable fire extinguishers have been inspected and serviced in accordance with BS 5306 Part 3, BAFE Scheme BSP101.

Clients, however, are reminded of the recommendations given in BS 5306 Part 3 for their own inspection:

It is recommended that regular visual inspections of all extinguishers be carried out by the user or the user's representative. The frequency of inspections should be at least monthly and, when circumstances require, inspections should be carried out more frequently.

**NOTE 1** The "Fire Safety: An Employer's Guide [10]" information leaflet for employers, which is published by the Home Office as guidance for operating within the Fire Precautions (Workplace) Regulations [2] and [3], suggests that good practice is to determine whether the extinguisher has been operated and to check for damage on a weekly basis.

Inspections should include checks that:

- a) each extinguisher is located in the designated place;
- b) each extinguisher is unobstructed and visible;
- c) the operating instructions for each extinguisher are clean and legible, and face outwards;
- d) each extinguisher has not been operated and is not obviously damaged;
- e) the reading of any pressure gauge or indicator fitted to an extinguisher is within operational safety limits;
- f) the seals and tamper indicators of each extinguisher are not broken or missing.

The client should arrange for corrective action, where necessary.

**NOTE 2** Employers in charge of a workplace have an obligation under the Fire Precautions (Workplace) Regulations [2] and [3]. Regulation [6] requires that, where it is necessary to provide extinguishing equipment to safeguard employees in the event of fire, this equipment has to be maintained in an efficient state, in efficient working order, and in good repair.



6 litre Water Extinguisher

Asset No	1	Location	Church side entrance	Next Test	<input type="text" value="09-2026"/>
Service	<input checked="" type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>
		Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>
		CallOut	<input type="checkbox"/>	New	<input type="checkbox"/>

2kg Carbon Dioxide Extinguisher

Asset No	2	Location	Church vestry	Next Test	<input type="text" value="09-2025"/>
Service	<input checked="" type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>
		Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>
		CallOut	<input type="checkbox"/>	New	<input type="checkbox"/>

2kg Carbon Dioxide Extinguisher

Asset No	3	Location	Church organ	Next Test	<input type="text" value="09-2024"/>
Service	<input checked="" type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>
		Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>
		CallOut	<input type="checkbox"/>	New	<input type="checkbox"/>

6 litre Water Extinguisher

Asset No	4	Location	Church fire exit rear	Next Test	<input type="text" value="09-2025"/>
Service	<input checked="" type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>
		Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>
		CallOut	<input type="checkbox"/>	New	<input type="checkbox"/>

6 litre Water Extinguisher

Asset No	5	Location	Chchurch side entrance	Next Test	<input type="text" value="09-2025"/>
Service	<input checked="" type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>
		Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>
		CallOut	<input type="checkbox"/>	New	<input type="checkbox"/>

2kg Carbon Dioxide Extinguisher

Asset No	6	Location	Church rear room	Next Test	<input type="text" value="09-2030"/>
Service	<input checked="" type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>
		Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>
		CallOut	<input type="checkbox"/>	New	<input type="checkbox"/>

6 litre Foam Extinguisher

Asset No	7	Location	Church bell tower	Next Test	<input type="text" value="09-2023"/>
Service	<input checked="" type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>
		Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>
		CallOut	<input type="checkbox"/>	New	<input type="checkbox"/>

2kg Carbon Dioxide Extinguisher

Asset No	8	Location	Church bell tower	Next Test	<input type="text" value="09-2024"/>
Service	<input checked="" type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>
		Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>
		CallOut	<input type="checkbox"/>	New	<input type="checkbox"/>



DELIVERY / INSTALLATION

2kg Carbon Dioxide Extinguisher

Asset No	9	Location	Hut	Next Test	09-2025									
Service	<input checked="" type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>	Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>	CallOut	<input type="checkbox"/>	New	<input type="checkbox"/>	

6 litre Foam Extinguisher

Asset No	10	Location	Hut	Next Test	09-2025									
Service	<input checked="" type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>	Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>	CallOut	<input type="checkbox"/>	New	<input type="checkbox"/>	

1.2m x 1.2m Fire Blanket

Asset No	11	Location	Vicarage kitchen	Next Test	10-2020									
Service	<input checked="" type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>	Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>	CallOut	<input type="checkbox"/>	New	<input type="checkbox"/>	New blanket to be sent in post.

6 litre Water Extinguisher

Asset No	12	Location	Floor 1 Vicarage stairwell	Next Test	10-2026									
Service	<input type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>	Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>	CallOut	<input type="checkbox"/>	New	<input checked="" type="checkbox"/>	Supplied as per quote

2kg Carbon Dioxide Extinguisher

Asset No	13	Location	Floor 1 Vicarage studio	Next Test	10-2031									
Service	<input type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>	Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>	CallOut	<input type="checkbox"/>	New	<input checked="" type="checkbox"/>	Supplied as per quote

6 litre Water Extinguisher

Asset No	14	Location	Ground vicarage entrance	Next Test	10-2026									
Service	<input type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>	Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>	CallOut	<input type="checkbox"/>	New	<input checked="" type="checkbox"/>	Supplied as per quote

2kg Carbon Dioxide Extinguisher

Asset No	15	Location	Ground vicarage entrance	Next Test	10-2031									
Service	<input type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>	Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>	CallOut	<input type="checkbox"/>	New	<input checked="" type="checkbox"/>	Supplied as per quote

6 litre Water Extinguisher

Asset No	16	Location	Ground vicarage hallway/stairs	Next Test	10-2026									
Service	<input type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>	Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>	CallOut	<input type="checkbox"/>	New	<input checked="" type="checkbox"/>	Supplied as per quote



**Red and White Fire Protection Limited**

**DELIVERY / INSTALLATION**

Schedule 21-10-00764

Inspected 21/10/2021

### Recommendations / Additional Notes

New equipment supplied and installed as per quote Q1092.  
Fire blanket to be sent in post as requested.