



Red and White Fire Protection Limited

Unit 8, Alpha Business Park

0800 058 8946

Travellers Close

info@redandwhitefireprotection.co.uk

Welham Green

www.redandwhitefireprotection.co.uk

Herts, AL9 7NT

FIRE EXTINGUISHER SERVICE INSPECTION CERTIFICATE

Client: St Andrews Church

Address: Silver Street, Enfield, EN13NG

This is to certify that a representative of Red and White Fire Protection Ltd has recently visited your premises to service your portable fire extinguishers and, apart from the non conforming extinguishers detailed, they have been serviced as required by British Standard BS 5306: part 3 2017. Certification is reliant on all extinguishers being in good, working and serviceable condition. If any equipment is found to be non conforming and could not be rectified at time of service, a recommendation to rectify will be supplied.

Date of Service: 05/11/2025

Job Reference: 25-11-03083

Next Service Due: 05/11/2026

Engineer: AC



Red and White Fire Protection Limited

Unit 8, Alpha Business Park

0800 058 8946

Travellers Close

info@redandwhitefireprotection.co.uk

Welham Green

www.redandwhitefireprotection.co.uk

Herts, AL9 7NT

GUIDANCE TO CLIENTS

Apart from the non-conforming extinguishers recorded, all portable fire extinguishers have been inspected and serviced in accordance with BS 5306 Part 3, BAFE Scheme BSP101.

Clients, however, are reminded of the recommendations given in BS 5306 Part 3 for their own inspection:

It is recommended that regular visual inspections of all extinguishers be carried out by the user or the user's representative. The frequency of inspections should be at least monthly and, when circumstances require, inspections should be carried out more frequently.

NOTE 1 The "Fire Safety: An Employer's Guide [10]" information leaflet for employers, which is published by the Home Office as guidance for operating within the Fire Precautions (Workplace) Regulations [2] and [3], suggests that good practice is to determine whether the extinguisher has been operated and to check for damage on a weekly basis.

Inspections should include checks that:

- a) each extinguisher is located in the designated place;
- b) each extinguisher is unobstructed and visible;
- c) the operating instructions for each extinguisher are clean and legible, and face outwards;
- d) each extinguisher has not been operated and is not obviously damaged;
- e) the reading of any pressure gauge or indicator fitted to an extinguisher is within operational safety limits;
- f) the seals and tamper indicators of each extinguisher are not broken or missing.

The client should arrange for corrective action, where necessary.

NOTE 2 Employers in charge of a workplace have an obligation under the Fire Precautions (Workplace) Regulations [2] and [3]. Regulation [6] requires that, where it is necessary to provide extinguishing equipment to safeguard employees in the event of fire, this equipment has to be maintained in an efficient state, in efficient working order, and in good repair.



INSPECTION SCHEDULE

6 litre Water Extinguisher

Asset No	1	Location	Church side entrance	Next Test	<input type="text" value="09-2026"/>									
Service	<input checked="" type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>	Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>	CallOut	<input type="checkbox"/>	New	<input type="checkbox"/>	<input type="text"/>

2kg Carbon Dioxide Extinguisher

Asset No	2	Location	Church vestry	Next Test	<input type="text" value="09-2035"/>									
Service	<input type="checkbox"/>	Condemn	<input checked="" type="checkbox"/>	Recharge	<input type="checkbox"/>	Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>	CallOut	<input type="checkbox"/>	New	<input checked="" type="checkbox"/>	<input type="text" value="Expired - replaced"/>

2kg Carbon Dioxide Extinguisher

Asset No	3	Location	Church organ	Next Test	<input type="text" value="09-2035"/>									
Service	<input type="checkbox"/>	Condemn	<input checked="" type="checkbox"/>	Recharge	<input type="checkbox"/>	Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>	CallOut	<input type="checkbox"/>	New	<input checked="" type="checkbox"/>	<input type="text" value="Expired - replaced"/>

6 litre Water Extinguisher

Asset No	4	Location	Church fire exit rear	Next Test	<input type="text" value="09-2035"/>									
Service	<input type="checkbox"/>	Condemn	<input checked="" type="checkbox"/>	Recharge	<input type="checkbox"/>	Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>	CallOut	<input type="checkbox"/>	New	<input checked="" type="checkbox"/>	<input type="text" value="Expired - replaced"/>

6 litre Water Extinguisher

Asset No	5	Location	Chchurch side entrance	Next Test	<input type="text" value="09-2030"/>									
Service	<input type="checkbox"/>	Condemn	<input checked="" type="checkbox"/>	Recharge	<input type="checkbox"/>	Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>	CallOut	<input type="checkbox"/>	New	<input checked="" type="checkbox"/>	<input type="text" value="Expired - replaced"/>

2kg Carbon Dioxide Extinguisher

Asset No	6	Location	Church rear room	Next Test	<input type="text" value="09-2030"/>									
Service	<input checked="" type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>	Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>	CallOut	<input type="checkbox"/>	New	<input type="checkbox"/>	<input type="text"/>

6 litre Foam Extinguisher

Asset No	7	Location	Church bell tower	Next Test	<input type="text" value="09-2028"/>									
Service	<input checked="" type="checkbox"/>	Condemn	<input type="checkbox"/>	Recharge	<input type="checkbox"/>	Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>	CallOut	<input type="checkbox"/>	New	<input type="checkbox"/>	<input type="text"/>

2kg Carbon Dioxide Extinguisher

Asset No	8	Location	Church bell tower	Next Test	<input type="text" value="09-2035"/>									
Service	<input type="checkbox"/>	Condemn	<input checked="" type="checkbox"/>	Recharge	<input type="checkbox"/>	Refurbish	<input type="checkbox"/>	Discharge	<input type="checkbox"/>	CallOut	<input type="checkbox"/>	New	<input checked="" type="checkbox"/>	<input type="text" value="Expired - replaced"/>



INSPECTION SCHEDULE

2kg Carbon Dioxide Extinguisher

Asset No 9 Location Hut Next Test 09-2025

Service Condemn Recharge Refurbish Discharge CallOut New Void - no access - no longer in use

6 litre Foam Extinguisher

Asset No 10 Location Hut Next Test 09-2025

Service Condemn Recharge Refurbish Discharge CallOut New Void - no access - no longer in use

1.2m x 1.2m Fire Blanket

Asset No 11 Location Vicarage kitchen Next Test 10-2020

Service Condemn Recharge Refurbish Discharge CallOut New

6 litre Water Extinguisher

Asset No 12 Location Floor 1 Vicarage stairwell Next Test 10-2026

Service Condemn Recharge Refurbish Discharge CallOut New

2kg Carbon Dioxide Extinguisher

Asset No 13 Location Floor 1 Vicarage studio Next Test 10-2031

Service Condemn Recharge Refurbish Discharge CallOut New

6 litre Water Extinguisher

Asset No 14 Location Ground vicarge entrance Next Test 10-2026

Service Condemn Recharge Refurbish Discharge CallOut New

2kg Carbon Dioxide Extinguisher

Asset No 15 Location Ground vicarage entrance Next Test 10-2031

Service Condemn Recharge Refurbish Discharge CallOut New

6 litre Water Extinguisher

Asset No 16 Location Ground vicarage hallway/stairs Next Test 10-2026

Service Condemn Recharge Refurbish Discharge CallOut New



Red and White Fire Protection Limited

INSPECTION SCHEDULE

Schedule 25-11-03083

Inspected 05/11/2025

Recommendations / Additional Notes

Annual service 2025

2 x Water, 3 x CO2 expired - replaced.